

First Alert – 13/04/2017

PLTR LNE & EM Peterborough- Cricklewood TRM



What happened?

During track renewal work a Track Renewal Machine (TRM) was moving sleepers into position when one end of a sleeper fell to track level.

A full exclusion zone was in place during the operation.

What are the details?

Although the lift was fully planned, the sleeper had not been fully secured in place and the movement of the lift dislodged one end.

There were no injuries or damage as a result of the incident.

What can we learn?

- Ensure all loads are 100% secure and all fixings seated correctly before completing planned movements.
- Ensure exclusion zones are in place and complied with.

A yellow semi-circle graphic containing the text 'ONE CULTURE TARGET ZERO' in white, stacked vertically.

ONE
CULTURE
TARGET
ZERO

First Alert – 13/04/2017

PLTR LNE & EM Peterborough- Cricklewood TRM

